XII. Specification of the Patent granted to Mr. FRANCIS FREDE-RICK ECKHARDT, of Sloane-street, Chelsea; for his Method of preparing linen and cotton Cloths with a Paste, so as to form a fmooth and regular Surface, and yet leave the Cloth of a pliable Quality, for the Purpose of receiving a Coat of water-fize Colours; upon which are afterwards printed Ornaments in fine Silver, and Gold, or Colours, in different Patterns, fo as to refemble Damask, Lace, and various filk Stuffs; which, being afterwards varnished, may be washed with Water without Injury; to be used for Hangings, and other Furniture for Rooms.

Dated April 30, 1793.

TO all to whom these presents shall come, &c.

Now know ye, that I the said Francis Frederick

rick Eckhardt, in pursuance of the faid proviso in the faid letters patent, do hereby describe and ascertain the nature of the said invention, and in what manner the same is to be performed as follows; that is to fay, prepare a paste with flour, starch, or any of the ingredients with which paste is or can be made with water or milk; when the paste is made, mix with it a sufficient quantity of wax, fo as to preferve the linen, cotton, or cloth, intended to be used, of a pliant or flexible quality. Then strain the linen, cotton, or cloth, upon a frame, and fill the pores or interstices with the above paste or composition; this is to be done fo as to render the furface as smooth as possible. When the linen or cloth is completely dry, lay on a proper coat of water-colours, mixed with gum or fize, according to the nature of the colour intended to be used; this being dry must be well fized over, and, when again dry, varnished over with any of the various forts of varnish which will resist water, as often as it shall be found necessary, according to the nature of the colour used. If it should be wished that ornaments in filver, gold; or colours, to refemble damask

3

damask lace, or any of the various filk stuffs, should be printed upon the linen or cloth, then, after the coat of water-colours has been laid on, and is dry, gold fize, or any of the other compositions that will answer the same purpose, must be laid, with a printing block or a brush, on those parts of the linen or cloth, upon which the ornaments are intended to be placed. Before the fize or composition is completely dry, gild or filver it with gold or filver leaves, so as to describe the ornaments: this being done, fize it over once or twice, as occasion may require; and when thoroughly dry, varnish it over with any of the varnishes, in the manner above mentioned. In witness whereof, &c.